

Machine	Location	Operating Instructions	Safety Information	Accessories
Carver Isostatic press and die set	Dow 2231		Pinch points, keep hands away from device while in use. Large pressure is created, wear safety glasses at all times.	Safety Glasses.
Computer	Dow 2224	-		Jade, Adobe Photoshop, Adobe Photoshop Elements (digital darkroom), Excel, Kaleidagraph, C-MOLD/MOLDFLOW
HP Nanovoltmeter	Dow 2219	-		-
Keithley Constant Current Source	Dow 2219	-		-
Lindberg Furnaces	Dow 2231	http://msewww.engin.umich.edu/research/researchfacilities/procedures/Lindberg_Furnace/		Thermal Gloves, Face shield, thermal apron and arm shields
Miniflex X-ray Diffraction System	Dow 2224	http://msewww.engin.umich.edu/research/researchfacilities/procedures/Miniflex/		Glass slides, radiation monitoring ring, clay
Nikon/Olympus Optical Microscopes	Dow 2224	http://msewww.engin.umich.edu/research/researchfacilities/procedures/Optical_Microscope/	Caution should be used when handling glass slides. Throw away broken glass slides in the Broken Glass Receptacle located in the front of room 2224.	Glass Slides, polarizing lens, clay
Voltmeter	Dow 2219			